

<b>Area:</b> Geraldton	<b>Place Number:</b> 77	<b>Category:</b> 3
<b>Assessment Date:</b> 25/10/1996	<b>Last Revision Date:</b> 27/10/2009	
<b>HCWA Number:</b> 13258	<b>Asset ID:</b> MCH126474	

### PLACE DETAILS

<b>Name:</b>	House
<b>Other Names:</b>	5 Conway Street
<b>Type of Place:</b>	House
<b>Address:</b>	5 Conway Street
<b>Suburb:</b>	Beachlands

### LOCATION

<b>Map Reference:</b>	14.14	<b>GPS Northing:</b>	6813907.00	<b>GPS Easting:</b>	265887.000
			0000		000



#### Photo Description:

20/11/2007

Rod Milne

Decorative timberwork a feature to the gable end.

## SITE DETAILS

<b>Lot No.:</b>	Lot 530	<b>Assess No.:</b>	10376
<b>Reserv No.:</b>		<b>Vol/Fol:</b>	
<b>Dia/Plan:</b>			

## USE OF PLACE

<b>Original Use:</b>	Residence		
<b>Current Use:</b>	Residence		
<b>Ownership:</b>			
<b>Public Access:</b>	No	<b>Occupied:</b>	Occupied

## DESCRIPTION

<b>Walls:</b>	Weatherboard	<b>Roof:</b>	Corrugated Iron
<b>Condition:</b>	Good	<b>Integrity:</b>	
<b>Original fabric:</b>	Wall cladding		
<b>Modifications:</b>	Roof cladding		

This is a timber framed weatherboard clad house with a hipped corrugated iron roof which extends to cover the verandahs to the front and east side. A gable roof is inset into the main roof to the northwest and the gable end features timber boards with timber braces to the eaves. Below the gable, a corrugated iron awning covers the window to the main room. The verandahs are supported on timber posts with criss-cross timber infill below the handrail. The windows are eight pane timber framed casement style. There is a brick chimney to the south west.

## HISTORY

<b>Construction Date:</b>	1970	<b>Source:</b>	
<b>Architect:</b>	Unknown		
<b>Builder:</b>	Unknown		

No History Available.

## HISTORIC THEMES

<b>HCWA:</b>	104 Land allocation and subdivision
<b>AHC:</b>	4.1.2 Making suburbs

## STATEMENT OF SIGNIFICANCE

This house has retained much of its original fabric and style including the weatherboard cladding, window awning and wrap around verandahs. It is a good example of weatherboard housing of its era and contributes to the streetscape of the locale.

## MANAGEMENT CATEGORY

**Management Category:** 3  
**Level of Significance:** MODERATE SIGNIFICANCE: Important to the heritage of the locality.  
**Management Recommendation:** Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

## OTHER LISTINGS

No other listings

## SUPPORTING INFORMATION

## OTHER PHOTOS



**Photo Description:**

25/10/1996

Suba & Grundy

Criss cross balustrade and window awning evident from street view.