

<b>Area:</b> Geraldton	<b>Place Number:</b> 84	<b>Category:</b> 4
<b>Assessment Date:</b> 25/10/1996	<b>Last Revision Date:</b> 27/10/2009	
<b>HCWA Number:</b> 13338	<b>Asset ID:</b> MCH126488	

### PLACE DETAILS

<b>Name:</b>	House
<b>Other Names:</b>	15 Conway Street
<b>Type of Place:</b>	House
<b>Address:</b>	15 Conway Street
<b>Suburb:</b>	Beachlands

### LOCATION

<b>Map Reference:</b>	14.14	<b>GPS Northing:</b>	6813893.00	<b>GPS Easting:</b>	265760.000
			0000		000



**Photo Description:**

20/11/2007

Rod Milne

View to house partly obscured by vegetation.

## SITE DETAILS

<b>Lot No.:</b>	Lot 525	<b>Assess No.:</b>	10371
<b>Reserv No.:</b>	1693	<b>Vol/Fol:</b>	
<b>Dia/Plan:</b>			

## USE OF PLACE

<b>Original Use:</b>	Residence		
<b>Current Use:</b>	Residence		
<b>Ownership:</b>	City of Geraldton-Greenough		
<b>Public Access:</b>	No	<b>Occupied:</b>	Occupied

## DESCRIPTION

<b>Walls:</b>	Brick	<b>Roof:</b>	Corrugated Iron
<b>Condition:</b>	Good	<b>Integrity:</b>	
<b>Original fabric:</b>			
<b>Modifications:</b>	Partial verandah infill		

This brick house has a gambrel corrugated iron roof with a hipped roof to the rear. The roof extends to cover the verandah to the north west which is supported on half timber posts with rendered masonry piers below. The verandah has a rendered masonry balustrade with breeze block infill above. The red brick walls have stucco finish to the upper third. There is a tall rendered chimney with brick corbelling to the east. A low fence of timber post and wire infill forms the property boundary.

## HISTORY

<b>Construction Date:</b>	unknown	<b>Source:</b>	K. Gallaher
<b>Architect:</b>	Unknown		
<b>Builder:</b>	Unknown		

No History Available.

## HISTORIC THEMES

<b>HCWA:</b>	104 Land allocation and subdivision 405 Sport, recreation and entertainment
<b>AHC:</b>	4.1.2 Making suburbs 8.9 Commemorating significant events and people

## STATEMENT OF SIGNIFICANCE

Although the verandah has been altered, this house has retained much of its original fabric including the face brickwork and tall chimney. Given this, the place contributes to the built environment of the locale.

## MANAGEMENT CATEGORY

<b>Management Category:</b>	4
<b>Level of Significance:</b>	SOME SIGNIFICANCE: Contributes to the heritage and/or historical development of the locality.
<b>Management Recommendation:</b>	Conservation of the place is desirable. Any proposed change to the place should be in sympathy with the heritage values of the place.

## OTHER LISTINGS

No other listings

## SUPPORTING INFORMATION

Gallaher, K., "List of Openings etc".  
"Geraldton Guardian & Express".

## OTHER PHOTOS



**Photo Description:**

25/10/1996

Suba & Grundy

Tall chimney punctuates the roof scape.