

Area: Geraldton	Place Number: 143	Category: 3
Assessment Date: 15/10/1996	Last Revision Date: 03/11/2009	
HCWA Number: 13393	Asset ID: MCH127111	

PLACE DETAILS

Name:	House
Other Names:	93 Fitzgerald Street
Type of Place:	House
Address:	93 Fitzgerald Street
Suburb:	Geraldton

LOCATION

Map Reference: 14.14	GPS Northing: 6814051.00	GPS Easting: 266446.000
	GPS Northing: 0000	GPS Easting: 000



Photo Description:

6/12/2007

Rod Milne

View of front facade.

SITE DETAILS

Lot No.:	Lot 123	Assess No.:	11152
Reserv No.:	29735	Vol/Fol:	
Dia/Plan:	220966		

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:	City of Greater Geraldton		
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Weatherboard	Roof:	Corrugated Iron
Condition:	Good	Integrity:	
Original fabric:	Largely intact		
Modifications:			

This timber framed and weatherboard clad house has a gambrel corrugated iron roof which extends to cover a small front verandah to the street facade which is supported on a turned timber post. The main roof also extends to the north to cover a verandah which is also supported on turned timber posts. Between the two verandahs to the north west there is a window with a ripple iron awning. To the south of the front verandah a gable roof covers the main room which also has a ripple iron window awning. Windows are timber framed casement style with french doors to the north verandah. There is a timber picket fence to the street boundary.

HISTORY

Construction Date:	unknown	Source:	HCWA RHP Documentation
Architect:	Unknown		
Builder:	Unknown		

No History Available.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
--------------	-------------------------------------

STATEMENT OF SIGNIFICANCE

This house has aesthetic appeal given that much of the original fabric is intact including the weatherboard cladding, turned timber verandah posts, window awnings and unusual window placement to the front facade. The place makes a high contribution to the streetscape of the area.

MANAGEMENT CATEGORY

Management Category: 3
Level of Significance: MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation: Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

Heritage Council of WA - Register, 22/04/2005

SUPPORTING INFORMATION

HCWA RHP Documentation; Gray, L., "Conservation Plan for Mullewa Railway Station Group", 2010; Barden, W.D., "Mullewa Through the Years 1861-1961", Mullewa Road Board, 1961; Keeffe, B., "Eastward Ho: To Mullewa and The Murchison", Mullewa Shire Council, 1995.

OTHER PHOTOS



Photo Description:

15/10/1996

Suba & Grundy

Previous fence since replaced.