

Area: Geraldton	Place Number: 182	Category: 3
Assessment Date: 14/10/1996	Last Revision Date: 19/11/2009	
HCWA Number: 13279	Asset ID: MCH126870	

PLACE DETAILS

Name:	House
Other Names:	34 Francis Street
Type of Place:	House
Address:	34 Francis Street
Suburb:	Geraldton

LOCATION

Map Reference: 14.15	GPS Northing: 6814127.00	GPS Easting: 266076.000
	GPS Northing: 0000	GPS Easting: 000



Photo Description:

31/10/2007

Rod Milne

New criss cross balustrade to verandah.

SITE DETAILS

Lot No.:	Lot 7	Assess No.:	10883
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Weatherboard/Fibro	Roof:	Corrugated Iron
Condition:	Good	Integrity:	
Original fabric:			
Modifications:			

This timber framed weatherboard house has a combination corrugated iron hipped and gable roof with a separate gable to a side room (north). The main roof covers verandahs to the north and east which are supported on timber posts with metal lace work brackets. Verandahs are partly enclosed at each corner with fibro. There is a lean-to roof to the rear which covers a fibro clad extension. There is a tall brick wall with double timber entry gates to the street boundary which partially obscures views to the house.

HISTORY

Construction Date:	1890	Source:	Shirley Scotter
Architect:	Unknown		
Builder:	Unknown		

This house was built in the early 1890s for the Bogle Family, who had interests in the Chapman and Jose cool drink factory. (Source: Shirley Scotter) Contact Ian Bogle for further information.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
--------------	-------------------------------------

AHC:

302 Rural industry and market gardening
603 Local heroes and battlers
4.1.2 Making suburbs
2.4.4 Migrating through organised colonisation
3.5.1 Grazing stock

STATEMENT OF SIGNIFICANCE

Although set behind a tall brick wall, the style of the house is still visible from the street. Elements such as the high pitched roof and surrounding verandahs give the place high streetscape value.

MANAGEMENT CATEGORY

Management Category: 3
Level of Significance: MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation: Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

Bibliography:
Feilman, M., "Greenough Historical Survey of the Front Flats", 1977 (1).
Suba, T., "The Greenough Front Flats Bibliography of Local Sources and Table of Heritage Places", 1994.
Correspondence from Dot Paparella, 12/12/1997.
HCWA Database No.03752.
Photographs:
GHS6225 cottage ruin (1988).

OTHER PHOTOS



Photo Description:

14/10/1996

Suba & Grundy

View of house partially obscured by brick wall.