

Area: Geraldton	Place Number: 366	Category: 3
Assessment Date: 24/10/1996	Last Revision Date: 12/03/2010	
HCWA Number: 13760	Asset ID: MCH126530	

PLACE DETAILS

Name:	House
Other Names:	109 Shenton Street
Type of Place:	House
Address:	109 Shenton Street
Suburb:	Geraldton

LOCATION

Map Reference: 14.14	GPS Northing: 6813761.00	GPS Easting: 266590.000
		000



Photo Description:

30/11/2007

Rod Milne

Front facade showing gable end decoration.

SITE DETAILS

Lot No.:	Lot 4	Assess No.:	10443
Reserv No.:		Vol/Fol:	
Dia/Plan:			

USE OF PLACE

Original Use:	Residence		
Current Use:	Residence		
Ownership:			
Public Access:	No	Occupied:	Occupied

DESCRIPTION

Walls:	Weatherboard	Roof:	Corrugated Iron
Condition:	Good	Integrity:	
Original fabric:			
Modifications:			

This timber framed weatherboard clad cottage has a gambrel roof with a gable roof to the front which is surrounded on three sides by a separate hipped verandah roof. The gable end has roughcast and timber batten infill with a small finial and pendant. The verandah is supported on turned timber posts and has a timber balustrade and decorative timber frieze. The verandah is accessed via a set of balustraded timber steps. Windows are timber framed and casement style to the front room, double hung with curved metal awnings to the side. There is a gambrel roof carport to the front garden and a picket fence with a small timber porch forms the street boundary of the place.

HISTORY

Construction Date:	unknown	Source:	
Architect:	Unknown		
Builder:	Unknown		

No History Available.

HISTORIC THEMES

HCWA:	104 Land allocation and subdivision
--------------	-------------------------------------

STATEMENT OF SIGNIFICANCE

This house has retained its original weatherboard cladding, turned timber posts and verandah balustrade, finial and gable end which enhances its authenticity. The house is representative of weatherboard clad houses of its era. The place makes an important contribution to the built environment of the locale

MANAGEMENT CATEGORY

Management Category: 3
Level of Significance: MODERATE SIGNIFICANCE: Important to the heritage of the locality.
Management Recommendation: Conservation of the place is recommended. Any proposed change to the place should not unduly impact on the heritage values of the place and should retain significant fabric wherever feasible.

OTHER LISTINGS

No other listings

SUPPORTING INFORMATION

Suba, T., "Jenner's House Rediscovered", MidWest Times, 30/11/1994.
GLLSPC - Chapman Road.

OTHER PHOTOS



Photo Description:

24/10/1996

Suba & Grundy

Front facade showing verandah details.